





Issues That Need to be Addressed

- Another nose/scattering chamber flange is currently being fabricated
 - Threaded holes in flange can be countersunk
 - This will take a few weeks
 - The ST/Target S.A. will be delayed significantly
 - Does this affect Spring commissioning?
- Removal of downstream tape
- Tilt of ST can still be seen by eye
 - Tim indicated if nominal tilt still existed they would not need to address the problem