

1. Did you do any FEA study of stresses on the bar box window if the box stands vertically ?

2. In case that LLAPD detectors are not ready, what is your fall back position ?

3. Considering that your tracks are nearly perpendicular, do you need a full detector coverage ?

