







MWPC Wire Stringing Update

Clean Room Layout






Carbon Tube Painting Procedure



- String wire through tube
- Place on end of detector
- Paint and let dry one day



Carbon Tube Wire Positioning



- Move wire to central region
- Position tube along wire using rulers to align properly